



**SECTION VIII – CONTROL MEASURES**

**Ventilation:** Provide local exhaust during processing.

**Respiratory Protection:** None required under normal processing conditions.

**Eye/Skin Protection:** Safety glasses

**Other Precautions:** Avoid contamination of tobacco products. Above 230 °C toxic gaseous products can be produced. Provide good ventilation or respirator if there is a probability of exceeding the 230 °C.

**SECTION IX – SPECIAL PRECAUTIONS**

**Precautions to be Taken in Handling and Storage**

Avoid contamination. Keep containers closed.

**USER'S RESPONSIBILITY**

This bulletin cannot cover all possible situations which the user may experience during processing. Each aspect of your operation should be examined to determine if, or where, additional precautions may be necessary. All health and safety information contained in this bulletin should be provided to your employees or customers. It is your responsibility to use this information to develop appropriate work practice guidelines and employee instructional programs for your operation.

**DISCLAIMER OF LIABILITY**

As the conditions or methods of use are beyond our control, we do not assume any responsibility and expressly disclaim any liability for any use of this material. Information contained herein is believed to be true and accurate but all statements or suggestions are made without warranty, express or implied, regarding accuracy of the information, the hazards connected with the use of the material or the results to be obtained from the use thereof. Compliance with all applicable federal, state and local laws and regulations remains the responsibility of the user.